



## 3-TRAPS SCHIJVEN

## 3-STUFENSCHLEIBEN

## 3-STEP PULLEYS

	D <sub>w1</sub>	D <sub>w2</sub>	D <sub>w3</sub>	D <sub>max.</sub>	D <sub>n</sub>	L	gewicht Gewicht weight
	(mm)						(kg)
<b>SPZ</b>	40	60	80	18	38	44	0,26
	50	70	90	22	38	44	0,35
	60	80	100	24	40	44	0,44
	80	100	120	26	45	44	0,54
	100	120	140	28	50	44	0,72
	120	140	160	28	50	44	0,84
<b>SPA</b>	50	70	90	22	40	52	0,42
	60	80	100	26	45	52	0,55
	70	90	110	26	45	52	0,62
	80	100	120	28	50	52	0,80
	90	110	130	28	50	52	0,85
	100	120	140	30	55	52	1,00
	120	140	160	32	60	52	1,22
	140	160	180	38	65	52	1,36
<b>SPB</b>	80	100	120	28	50	66	1,20
	100	120	140	28	50	66	1,40
	120	140	160	32	60	66	1,72
	140	160	180	38	65	66	2,40
	160	180	200	40	70	66	2,60

## 4-TRAPS SCHIJVEN

## 4-STUFENSCHLEIBEN

## 4-STEP PULLEYS

	D <sub>w1</sub>	D <sub>w2</sub>	D <sub>w3</sub>	D <sub>w4</sub>	D <sub>max.</sub>	D <sub>n</sub>	L	gewicht Gewicht weight
	(mm)							(kg)
<b>SPA</b>	50	70	90	110	22	45	68	0,69
	60	80	100	120	28	50	68	0,90
	70	90	110	130	28	50	68	1,00
	80	100	120	140	30	55	68	1,20
	90	110	130	150	30	55	68	1,30
	100	120	140	160	32	60	68	1,40